

Survey of Section T. R.



FIELD NOTES.

Witness Trees	Inches in Diameter	Bearings	Distances in Links	Witness Trees	Inches in Diameter	Bearings	Distances in Links
A { P. ...	14	N 36° W	64				
H. ...	6	N 32½° W	70½				
B { Hackberry	15	S 5° E	14				
elm	3	S 52½° W	101½				
C { elm	3	S 30° E	17½				
elm	8	S 30° W	16				
D { Hackberry	6	N 73° W	54				
E { sugar	2	S 29° E	25				
F { hove	3	N 48° E	8¾				
hove	6	N 76½° E	8½				

